

### City Manager's Office

City of Arts & Innovation

March 25, 2016

Sven E. Rodenbeck, Sc.D., P.E., BCEE Rear Admiral (retired), USPHS ATSDR/DCHI - Mailstop F59 1600 Clifton Road, NE Atlanta, GA 30329-4027

SUBJECT: PUBLIC HEALTH ASSESSMENT FOR THE NEIGHBORHOODS SURROUNDING THE

RIVERSIDE AGRICULTURAL PARK

Dear RADM Rodenbeck:

On behalf of the City of Riverside and its residents, I petition the Agency of Toxic Substances and Disease Registry (ATSDR) to conduct a public health assessment of the neighborhoods surrounding the approximately 62-acre undeveloped site known as Riverside Agricultural Park (Ag Park, Attachment 1). Residents in the area allege serious health issues that they believe are associated with environmental conditions at Ag Park. ATSDR involvement is needed to address these serious concerns. The City – in consultation with the Center for Community Action and Environmental Justice – requests that all properties within ½ mile of the Ag Park site be included in the public health assessment (Attachment 2). Attachments and links to relevant documents are noted below to provide ATSDR with the necessary backup materials.

Ag Park is located immediately west of the intersection of Rutland Avenue and Jurupa Avenue. Prior use of the site included, but was not limited to, the operation of a sewage treatment plant between 1942 to 1962. The sewage treatment plant accepted waste from industrial, commercial, and residential customers. The property is currently vacant and planned for residential development. The site is surrounded by well-established single-family residences to the east, south and west; the Santa Ana River borders Ag Park to the north.

On March 15, 2016, the California Department of Toxic Substances Control (DTSC) presented to the City Council of the City of Riverside the results of its re-evaluation of Ag Park. The DTSC presented its findings, as well as those of the United States Environmental Protection Agency (EPA), of past and current cleanup activities, soil sampling and the results of its testing; the site had previously been cleared for development by the DTSC, but was re-evaluated in response to the concerns expressed by residents of the surrounding area. The results of the re-evaluation indicate that elevated levels of polychlorinated biphenyls (PCBs) were identified on portions of the site.

We understand that ATSDR has cooperative agreements in place with related state agencies, and will actively engage them as appropriate.

Should you have any questions or if I can be of any assistance in the interim, please do not hesitate to contact me by phone at (951) 826-5553.

Sincerely,

John A. Russo City Manager


cc: California Department of Health Sciences – Environmental Health Investigation Branch
Desert Sierra Cancer Surveillance Program
Center for Community Action and Environmental Justice

#### Attachments:

- 1. Riverside Agricultural Park Map
- 2. Tentative Area for Public Health Assessment
- 3. Presentation of the California Department of Toxic Substances Control March 15, 2016

### Riverside Agricultural Park Documents:

- California Department of Toxic Substances Control Fact Sheet on the Re-Sampling of the Riverside Agricultural Park and Notice of Additional Cleanup: <a href="https://www.dtsc.ca.gov/SiteCleanup/Projects/upload/Riverside Agricultural Park CU-Re-Sampling Update.pdf">https://www.dtsc.ca.gov/SiteCleanup/Projects/upload/Riverside Agricultural Park CU-Re-Sampling Update.pdf</a>
- 2. California Department of Toxic Substances Control Riverside Ag Park website: <a href="http://www.dtsc.ca.gov/SiteCleanup/AgPark/AgPark.cfm">http://www.dtsc.ca.gov/SiteCleanup/AgPark/AgPark.cfm</a>
- 3. California Department of Toxic Substances Control EnviroStor Riverside Agricultural Park: <a href="http://www.envirostor.dtsc.ca.gov/public/profile-report.asp?global-id=33490087">http://www.envirostor.dtsc.ca.gov/public/profile-report.asp?global-id=33490087</a>



Imagery ©2016 Google, Map data ©2016 Google 200 ft



# Riverside Ag Park Update City Council Meeting City of Riverside

March 15, 2016
Barbara Lee
Director



Cal/EPA




- Overview & History
- Riverside Ag Park On-site Re-evaluation
- Soil & Groundwater Sampling
- Phase 3 Cleanup & Next Steps
- Riverside Ag Park Off-Site Evaluation
- Lessons Learned & Future Work
- Questions





## Riverside Agricultural Park







# Before Phase I & 2 Cleanup









### After Phase I & 2 Cleanup





Department of Toxic Substances Control



# March 2015 – Meeting with Riverside Ag Park Community









# ON-SITE RE-EVALUATION



- Collaborated with Water Board and AQMD
- Requested further review by US Army Corps of Engineers
- Requested EPA support and review
- Review included:
  - Detailed historical on-site activities
  - Evaluation of removal process of on-site sewer line
  - Analysis of records of offsite disposal of soil
  - Re-evaluation of analytical data for PCBs, metals, VOCs, SVOCs,
     Pesticides, Perchlorate and Dioxins/Furans
  - Collaborative review of air monitoring logs and data with AQMD
  - Soil and groundwater sampling for PCBs, metals and dioxin/furans
  - Analysis of PCB congeners in select samples
  - Re-evaluation of health risk using latest data



Cal/EPA



- The Santa Ana Regional Water Quality Control Board concluded:
  - Sampling of ground water onsite and offsite, and Santa Ana River streambed and sediment showed no impact to groundwater or sediment
  - Investigation of reports of illegal disposal of materials from the site showed complaints were unfounded
- Groundwater testing begun in 2015 indicates no impact to water resources







- The South Coast Air Quality Management District concluded:
  - Cleanup activities at the site were not subject to AQMD Rule 1150
  - AQMD Rule 403 requires fugitive dust, as demonstrated by upwind and downwind monitoring, not exceed 50 ug/m3
  - Review of upwind/downwind data from 131 days found 75 readings where the difference was greater than 50 ug/m3 but only 6 readings on 5 separate days where the concentration was greater downwind than upwind (updated 3/17/16 to correct earlier version)
  - The readings were not simultaneous so there were no violations
- Between July 23, 2013 and December 12, 2013, a total of 647,619 gallons of water was applied for dust suppression at the site
- Daily downwind air samples were collected for the first two weeks of excavation, after which samples were collected weekly; samples were analyzed for the presence of PCBs, which were not present in any samples





# Dust Suppression Activities





Department of Toxic Substances Control





- There are between 5,000 and 10,000 Formerly Used Defense Sites (FUDS) in the US, and nearly 669 in California
- Camp Anza is listed as a FUDS
- Ag Park is located within Camp Anza but not listed individually
- Reviews for possible Unexploded Ordnance in 1999 (INPR) and 2005 (ASR) by the Army Corps placed Camp Anza in the category of sites with "Negligible Explosive Safety Risk" requiring no further action
- At DTSC's request, the Army Corps has agreed to expedite the preliminary FUDS evaluation of the Camp Anza site, to begin in April 2016, and conclude by September, 2017







- The Santa Ana RWQCB has been leading a review and removal of 31 underground fuel storage tanks throughout the former Camp Anza site
- Of the 31 underground tank projects, all except 2 have been closed
- The Santa Ana RWQCB is leading a groundwater cleanup for contamination associated with operations by B.F. Goodrich/ROHR Industries on a portion of the former Camp Anza site
- US EPA has initiated review of contamination associated with B.F. Goodrich/ROHR Industries operations




# SOIL & GROUNDWATER SAMPLING - 2015

## Sampling – September 2015



- 88 discrete soil samples
- Installation of 2 groundwater wells















- Step by step collaboration
- Approval of sampling strategies
- Collection of co-located samples, analyzed at EPA lab
- Coordinated data analysis



Department of Toxic Substances Control













- Two groundwater wells installed in September
- Samples taken in September, December, and March
- Samples analyzed for PCBs, metals, dioxins/furans and perchlorate
- Groundwater monitoring reports available on DTSC website in EnviroStor database

	ag:s	Metals	Dioxins/Furans	Parchlorate
September	ND	In range for region	Toxic Equivalency Units (TEQ) = 0.0	One well = 4.1 ug/L (Flagged) and one well = ND
December	ND	In range for region	Toxic Equivalency Units (TEQ) = 0.0	Both wells ND








- Non-detect: below analytical laboratory detection limits (0.07 mg/kg or less)
- Screening Level: at one in a million (10<sup>-6</sup>) cancer risk; 0.22 mg/kg was used as conservative goal for Phase 2 cleanup
- Health Protective Level: for residential setting and within agencies' acceptable risk range, I mg/kg
- Hazardous Waste: 50 mg/kg
















PCB Level Messured	Non Detect	Below Screening Lavel	Below Health Level	Above Health Level	Hazardous Waste
		Less than 0.22 mg/kg	0.22 to 1.0 mg/kg	1.0 to 50.0 mg/kg	Above 50.0 mg/kg
Number of Samples	32	30	16	4	0

- Grid number B4 (in the west side of the site near this gully) has the highest concentration of 18 mg/kg; Grid number F3 has a concentration of 1.9 mg/kg in the surface sample.
- Results indicated previously undiscovered pockets of PCBs needing further investigation.
















### November 2015 Sampling Locations










PCB Level Measured	Non Detect	Below Screening	Below Health	Albove Health	Hazardous Waste
		Level .	Leval	Lava	
		Less than 0.22 mg/kg	0.22 to 1.0 mg/kg	1.0 to 50.0 mg/kg	Above 50.0 mg/kg
Number of Samples	43	44	54	31	4

- 4 samples were above 50 mg/kg, all located in a single, isolated area (western gully) outside proposed development area.
- Further cleanup is required before development can continue.
- Samples split between EPA and the commercial laboratory showed consistent variance; EPA and DTSC analyzing causes
  - Both labs used EPA method 8082 (updated 3/17/16 to correct earlier version)





### **November 2015 Sample Result Ranges**





# ° PHASE 3 CLEANUP



- Remove all known PCBs above original cleanup goal of 0.22 mg/kg
- Cleanup set at a level to ensure that adults and children can safely live here for decades
- Since soil is made up of many differing types of materials, DTSC will conduct statistical analysis to ensure cleanup goal is met







- Cleanup designed around uses and lot types
  - "Cut" residential lots
  - "Fill" residential lots
  - Areas outside current residential lots
- After the site-wide cleanup, additional verification sampling of each residential lot, and additional cleanup, if needed








# Cleanup for Cut Lots

















- Collect step-out soil samples in four directions at 25 feet and 50 feet from November 2016 sample locations exceeding PCB 0.22 mg/kg
- Remove soil around sample location exceeding cleanup goal to I foot deep and out to step-out sample limits (minimum 50 foot by 50 foot square excavation).
- Collect one bottom sample per 1,000 square feet with a minimum of three samples per removal area.
- If any results are above 0.22 mg/kg in any sample, continue step-out and deeper sampling until results are below cleanup goal (0.22 mg/kg).

  Department of Toxic Substances Control

  Cal/EPA




# Cleanup for Fill Lots







# Detail for Fill Lot Cleanup









- Collect step-out soil samples in four directions at 60 feet from sample location with PCB exceeding 0.22 mg/kg
- Remove soil around sample location exceeding cleanup goal to 1 foot deep and out to step-out sample limits (minimum 120 foot by 120 foot square)
- Collect one bottom sample per 1,000 square feet with a minimum of three samples per removal area.
- Continue step-out sampling an additional 10 feet laterally and 1 foot deep until results are below cleanup goal.







#### Cleanup for Areas Outside Current Residential Lots





Department of Toxic Substances Control





- Re-sample the outside areas on a 62.5 foot grid.
- If a historic data point is within 2 feet of the grid point and is below the cleanup goal then no sample required.
- Collect step-out soil samples in four directions at 25 and
   50 feet from sample location exceeding PCB cleanup goal.
- Remove soil around sample location exceeding cleanup goal to I foot deep and out to step-out sample limits (minimum 50 foot by 50 foot square excavation).
- Collect one bottom sample per 1,000 square feet with a minimum of three samples per removal area.
- Continue step-out sampling an additional 10 feet laterally and I foot deep until results are below cleanup goal.





#### Lot by Lot Confirmation Sampling After Cleanup










- After the cleanup of the entire site, additional confirmation sampling will be conducted for each residential lot
- For small lots, collect 6 samples per lot (2 front yard, 2 side yard, and 2 back yard
- For large lots, collect 8 samples per lot (2 front yard, 2 side yard, and 4 back yard.
- For cut lots, collect only surface samples (0-6 inches).
- For fill lots, collect surface samples, two foot deep samples, and for fill 8 feet or deeper, 50% of the depth of the fill (not including concrete fill material).
- For all lots, if any result exceeds the cleanup goal, remove soil in the area 2 feet deep and laterally to adjacent sample location meeting the cleanup goal, then resample including bottom samples.
- Continue removing and sampling until results are below cleanup goal.












Department of Toxic Substances Control



### Confirmation Sampling of Large Lot







#### Phase 3 Cleanup – EPA Conclusions

Sampling results show "low level contamination with a few elevated areas."

Fully expect that the data "will validate that the Site [Ag Park] is ready for residential development."







#### Next Steps - Riverside Ag Park (on-site)

- AQMD recommendations on Air Monitoring Plan will be incorporated
- Public review ends March 21st
- Sampling scheduled to begin March 22
- Phase 3 cleanup scheduled to start in late March to early April
- AQMD will provide compliance oversight during cleanup





# OFF-SITE EVALUATION



#### Riverside Ag Park Off-site Evaluation

- Army Corps of Engineers developing Preliminary Assessment for former Camp Anza
- Collaborating with Water Board on their involvement with former Camp Anza and Rohr
- DTSC contacted CCAEJ to review materials scheduled for March 15 and 21
- DTSC, EPA and Cal-EPA work group
- AQMD conducting air modeling
- Contacted health agencies to address community health concerns
- Establishing an off-site evaluation work group







### Off-site Community Work Group

- 3 to 5 community liaisons based on a request for membership
- DTSC will facilitate, with EPA participation
- CCAEJ identified as an advocacy stakeholder
- City of Riverside, Army Corp of Engineers and elected officials will be engaged as stakeholders
- 6 month planned duration
- Monthly in-person meetings at a location in the neighborhood
- Re-assessment of goals will take place at the end of the 6 months, and extended if needed





## LESSONS LEARNED & FUTURE WORK



- Review site characterization and sampling: consider use of multi-incremental sampling
- Review procedures for soil investigation and cleanup of PCB contamination
- Enhanced review of future incoming voluntary agreement requests
- Further evaluation of variability in EPA test methods











